

Villeneuve Tank Lines

R.R.1, DYER ROAD, MAXVILLE, ONTARIO K0C 1T0
OFFICE (613) 538-2461 - FAX (613) 538-2452



TO WHOM IT MAY CONCERN:

We installed a Kleenoil filter unit on a 3406C Caterpillar engine. We did oil sampling on the engine at regular intervals up to 160,000 kilometers with no breakdown of the oil. Every unit we have purchased has had a Kleenoil filter installed on it. We operate a local and a long distance fleet. Prior to installing the Kleenoil filter units we used to change the main and rod bearings on our Tandem Milk Trucks at approximately 200,000 kilometers due to the effect of the liquid load shifting back and forth in the tank with no baffles. Now we do not bother to check the bearings until we do an inframe because there is very little wear on them.

On our Long Distance Highway Tractors we do not look at or change the rod and main bearings as we used to do in the past.

When the valve cover is removed the top of the valve train is very clean with no deposits of carbon or sludge. We run around 150 power units and I would not think of not installing a Kleenoil filter unit on any of them.

Yours truly,

A handwritten signature in black ink that reads "Glen MacDonald".

Glen MacDonald
Maintenance
Supervisor Villeneuve
Tank Lines Villeneuve
Milk Transport